
Subject: FW: HYUNDAI IMAGEAUEST CO., LTD., FCC ID: PJILT20A0000, Assessment NO.: AN04T4073, Notice#1

Dear Mike Kuo,

We always appreciate your kind cooperations on our TCB applications.
We are very sorry to have kept you wating a reply.

Answer #1: We uploaded the corrected Block Diagram on your web site.

Please check & progress these applications.
If you have any questions or comments, please do not hesitate to contact us.

Thanks & Best regards,

Byung Ki Ham

Product Compliance Team
Hyundai Calibration & Certification Technologies Co., Ltd.

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]
Sent: Monday, July 26, 2004 5:06 PM
To: mkuo@ccsemc.com
Subject: HYUNDAI IMAGEAUEST CO., LTD., FCC ID: PJILT20A0000, Assessment NO.: AN04T4073, Notice#1

Question #1: The Block Diagram does not include information about local oscillator or crystal frequencies. Please provide.

Best regards,
Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.