

The Linksys Group Inc.

17401 Armstrong Ave., Irvine CA 92614 U.S.A.

FCC Labeling Requirements and Information

2002/12/06

American Telecommunications Certification Body, Inc.

6731 Whittier Avenue

Suite C110

McLean, VA 22101


RE : FCC Labeling Requirements

FCC ID : PKW-NWR04B


The following label information is required by the FCC Rules and Regulations for certified devices. Also attached, please find marketing information required by the FCC Rules and Regulations.

Thank you for your attention to these matters.


Sincerely,



(Even Hong)



2:1



Color


■ **Black**

NOTE:

1. 銀絲龍
2. **SIZE:59.5x25.8mm**
3. **Tolerance ± 0.1mm**

Part Number:	WR1133#LK
File Name:	LBWR1133-R0E-LK100
Version:	V1.0
Date:	10/08/2002
Software:	CoreIDRAW 9.0
Prepared by :	Erica ext. 6104
Approve by :	=

1:1



NON




This device complies with part 15 of the FCC rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference.
(2) This device must accept any interference received, including interference that may cause undesired operation.

NOTE:

1. 反銀龍貼紙
2. 尺寸: 31x12.7mm
3. 容許誤差 +/- 1 mm

Part Number:	WR1133#NE
File Name:	LBWB1000-ROM-LK110
Version:	V1.0
Date:	10/31/2002
Software:	CoreIDRAW 9.0
Prepared by :	Erica ext. 6104
Approve by :	=

LABEL Format:

	Wireless Cable/DSL Router with 4-Port Switch	
S/N	<input type="text"/>	FCC ID: PKW-MWR04B
MAC	<input type="text"/>	 PER HOME OR OFFICE USE
Made In Taiwan		

**This device complies with part 15 of the FCC rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference.
(2) This device must accept any interference received, including
interference that may cause undesired operation.**

LABEL Position:

