

INTERTEK TESTING SERVICES


Report No.: 0417097  
 Model No.: PM93259A

hp

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement MKR 1.6870 msec

REF -20.0 dBm AT 10 dB .06 dB

PEAK  
 LOG  
 10  
 dB/



WA SB  
 SC LS  
 CORR

Tested By: [Signature]  
 ( Gary Li )  
 Date: 6/9/04  
 Checked By: [Signature]  
 ( Ivan Wong )  
 Date: 22/9  
 Test Result: Pass / Fail /  NA

CENTER 27.145 MHz SPAN 0 Hz  
 #RES BW 3.0 MHz #VBW 3 MHz #SWP 75.0 msec

INTERTEK TESTING SERVICES

Report No.: 0417097  
Model No.: PM93259A

hp

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement


MKR 1.6500 msec

REF -20:0 dBm

AT 10 dB

.23 dB

PEAK  
LOG  
10  
dB/



WA SB  
SC LS  
CORR

Tested By: *Gary Li*  
( Gary Li )

Date: 10/9/04

Checked By: *Ivan Wong*  
( Ivan Wong )

Date: 23/9

Test Result: Pass / Fail / NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 15.0 msec

INTERTEK TESTING SERVICES

Report No.: 041797  
Model No.: PM93259A

hp


Pursuant to FCC Part 15 Section 15.221 Emissions Requirement MKR 713.00  $\mu$ sec

REF -20.0 dBm

AT 10 dB

3.47 dB

PEAK  
LOG  
10  
dB/



WA SB  
SC LS  
CORR

Tested By: [Signature]  
( Chey Li )

Date: 10-9-08

Checked By: [Signature]  
( Ivan Wong )

Date: 23/9

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 15.0 msec