

To: <TRJ@adelphia.net>
Cc: <jtchen@itslabtest-twn.com>, "Tulip Hu ITS/EMC-TPE" <Thu@itslabtest-twn.com>, "Elton Chan ITS/EMC-TPE" <Echan@itslabtest-twn.com>, "Cindy Chu ITS/EMC-TPE" <Cchu@itslabtest-twn.com>, <whgraff@qwest.net>
Subject: RE: FCC TCB Application Error Notification

Dear Timothy,

Enclosed please find the answer of review comments (FCC ID: PNK2G4-CM)

Answer :

1. Our client has modified the label and take off the FCC logo.
The file name: Label.pdf
2. Our client has added the information specified by 15.19(a)(3) at the label, but the description on the label is too small to see clearly.
Is this description essential?
The file name: Label.pdf
3. The set-up photo and test data were modified as attached.
The file name: Ce.pdf
4. We used two type of antenna for this testing, one is EMCO 3115(1-18GHz) an other is Schwarzbeck BBHA9170 (14-40GHz), the details of antenna please see section 2.4 of report.. Refer to the file name:010791
5. The data has been update. Please see section 3.5 of report. refer to the attach file name: 010791
6. 800~1600mW is Power Consumption of the EUT, not RF output power, the update manual was attached as filename: manual.
7. The FCC require statements has been added in manual of page 4, please see the attached filename: manual.

If you need more information please fell free to contact me.

Best regards.

Lyn Yang

ETL Semko TWN EMC Lab

Tel +886-3-519-1411 Ext 303

Fax +886-3-519-1410

E-mail: lyang@itslabtest-twn.com