



SOMA Networks, Inc.

185 Berry Street, Suite 4600 • San Francisco, California 94107

July 20, 2006

ATTN:Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

RE: Tune-up Procedure for SOMAport3, Model # CPE-300-2C0, FCC ID:
POZCPE700006553D

To Whom It May Concern:

The EUT with SOMA Model number CPE-300-270 is tuned and calibrated solely during the manufacturing process at the factory. It is neither necessary nor possible for a user to perform such a tune-up procedure.

Sincerely,

A handwritten signature in black ink, appearing to read "Robin Grindley".

Robin Grindley
Chief Scientist – Hardware Systems
SOMA Networks, Inc.