



June 02, 2006

RE: FCC ID: PPIRM-167_ATCB003491

Attention: Dennis Ward

Following answers regarding your questions of May 25, 2006:

Answer 1.

3 probes were used in the testing. The calibration information for S/N 1786 was erroneously omitted from the SAR report; please find the relevant pages from the calibration report in "ET3DV6 - SN1786 Feb 21, 2006-relevant pages.pdf".

Answer 2.

2 System Check tables are presented in Section 4.3.2 of the SAR report; the first one is for Head Tissue Simulants, the second is for Body Tissue Simulants. The probes were used on the following days for System Checking and for Device measurements:

- S/N 1786: on 3rd May 2006 for 850MHz head tissue simulant
- S/N 1808: on 19th April 2006 for 850MHz head tissue simulant
- S/N 1813: on 18th April 2006 for 850MHz body tissue simulant
- S/N 1813: on 24th April 2006 for 1900MHz body tissue simulant
- S/N 1813: on 25th April 2006 for 1900MHz head tissue simulant