

Patient Monitoring  
Quality & Regulatory Group  
3000 Minuteman Road  
Mailstop 4304  
Andover, MA 01810  
Tel: (978) 659-4348  
Fax: (978) 659-4481

22 January 2015

Reference: FCC ID PQC-4843C

Subject: Class II Permissive Change of Philips Telemetry 1.4 GHz Access Point ITS4843C

To Whom It May Concern;

Philips has replaced the power amplifier chip in the Philips Telemetry 1.4 GHz Access Point ITS4843C (FCC ID: PQC-4843C). We are no longer able to obtain the Murata power amplifier chip so it is being replaced with Triquint TKP770001 power amplifier chip.

The characteristics of the new chip are as follow:

- (i) The new chip component is identical in pin placement on the radio board.
- (ii) The new chip has the same functionality as the old chip, although internal circuitry may differ.
- (iii) Radio parameters are identical as with the old chip.
- (iv) The same conditions apply when a small area (approximately the same area as the chip) of the PCB is replaced with an equivalent chip.

Sincerely,



Delroy Smith