


BOTTOM SIDE VIEW

Secondary Side



Note (cont.):

- 9. Label (item 6) is placed directly on the flex substrate (item 1), inside the rectangle marked on the silkscreen.
- 10. Battery orientation is marked by a (+) sign on the silkscreen. Battery must be glued om the flex with item 3; see 950022.
- 11. Encapsulant (item 4) is applied only over marked areas; see doc. 950022.
- 12. Reference documentation:
 - Electrical Schematic PT21 – dwg. 900050 rev -; Electrical Schematic TEM21 – dwg. 900045 rev A;
 - Test Procedure Postag PT21, General Assy – doc. 950020, rev -.
 - Technological Instructions Postag PT21 – doc. 950022, rev -.
 - Technical Specifications Postag PT21 – doc. 950025, rev A.
 - Manufacturing Tree Postag PT21 – doc. 700034, rev A.
- 13. BOM for Postag PT21 General assy – doc. 700036, rev A.

					Lyngsoe Industries			NAME Postag PT21 Component Assembly		
								PART NO 600001	DWG NO 900054	REV A
A	610	MPAU	MHUZ	05Feb02	Dsg	MPAU	05Nov01			
REV	ECO NO	BY	CHK	DATE	Chk	MHUZ	05Nov01			
All rights strictly reserved. Reproduction or issue to third parties in any form whatever is not permitted without written permission from Lyngsoe Industries.					Aprv	DFER	05Nov01	SCALE	— —	SIZE A
										SHEET 2 of 2