

---

**INTERTEK TESTING SERVICE**

Report No.: 16040546HKG-003  
16040546HKG-004

**Equipment Photographs**

**Model : 44547RX**

**(Internal)**



---

## INTERTEK TESTING SERVICE

---

Report No.: 16040546HKG-003  
16040546HKG-004

### Equipment Photographs

Model : 44547RX

(Internal)



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

## INTERTEK TESTING SERVICE


---

Report No.: 16040546HKG-003  
16040546HKG-004

### Equipment Photographs

Model : 44547RX

(Internal)



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

## INTERTEK TESTING SERVICE


---

Report No.: 16040546HKG-003  
16040546HKG-004

### Equipment Photographs

Model : 44547RX

(Internal)



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

## INTERTEK TESTING SERVICE

---

Report No.: 16040546HKG-003  
16040546HKG-004

### Equipment Photographs

Model : 44547RX

(Internal)



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

## INTERTEK TESTING SERVICE


---

Report No.: 16040546HKG-003  
16040546HKG-004

### Equipment Photographs

Model : 44547RX

(Internal)



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

# INTERTEK TESTING SERVICE



---

Report No.: 16040546HKG-003  
16040546HKG-004

## Equipment Photographs

Model : 44547RX

(Internal)



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

**INTERTEK TESTING SERVICE**


---

Report No.: 16040546HKG-003  
16040546HKG-004

**Equipment Photographs**

**Model : 44547RX**

**(Internal)**



**Equipment Photographs**

---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX



---


## INTERTEK TESTING SERVICE

---

Report No.: 16040546HKG-003  
16040546HKG-004

**Model : 44547RX**

**(Internal)**



---

FCC ID: PQN44547RX2G4  
IC: 4438B-44547RX

---

**INTERTEK TESTING SERVICE**

Report No.: 16040546HKG-003  
16040546HKG-004

**Equipment Photographs**

**Model : 44547RX**

**(Internal)**

