


INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)



FCC ID: PQN91826RX2G4
IC: 4438B-91826RX



INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)



FCC ID: PQN91826RX2G4
IC: 4438B-91826RX


INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)



FCC ID: PQN91826RX2G4
IC: 4438B-91826RX



INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)



FCC ID: PQN91826RX2G4
IC: 4438B-91826RX



INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16041174HKG-003(FCC)
16041023HKG-004 (IC)

Equipment Photographs

Model : 91826RX

(Internal)

