



AUDIX Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan


Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2016/03/26	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	III
		Frequency	TX 5745MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0	







Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0	







Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11a	UNII Band	III
		Frequency	TX 5825MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		0	







Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5180MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	







Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5200MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	





Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5240MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	







AUDIX Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
 Fax: +886 2 26099303

Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5260MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	







AUDIX Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan


Tel: +886 2 26099301
 Fax: +886 2 26099303


Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5300MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	







Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5320MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	







Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5500MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	





Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5580MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	







AUDIX Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan


Tel: +886 2 26099301
 Fax: +886 2 26099303


Test Date	2016/03/29	Temp./Hum.	25°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5700MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	





Test Date	2016/03/29	Temp./Hum.	26°C/60%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5745MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	





AUDIX Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2016/03/29	Temp./Hum.	26°C/60%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	8dB	Test Voltage	DC 3.3V
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	

