


Issued on Aug. 15, 2005

# 5.7.7. Photographs of Conducted Emission Test Configuration



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 35 of 59 Issued Date : Aug. 15, 2005

Report No.: FR551937



Issued on Aug. 15, 2005



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 36 of 59

Report No.: FR551937


Issued Date : Aug. 15, 2005



Issued on Aug. 15, 2005

# 5.8.10. Photographs of Radiated Emission Test Configuration

#### Tx Mode



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 53 of 59

Report No.: FR551937

Issued Date : Aug. 15, 2005



Issued on Aug. 15, 2005

## **Charger Mode**



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 54 of 59

Report No.: FR551937

Issued Date : Aug. 15, 2005