

September 7, 2005  
RE: Wistron Corporation  
FCC ID: PU54P1091

Dear Bill,  
Here are our answers

1.) The Manual has omitted any required RF Exposure statements. In this case, the “no colocation” statements would apply. Please correct.

ANS: An updated manual was uploaded

2.) The Manual lacks the required “information to user” statement of 15.21. Please review.

ANS: An updated manual was uploaded

3.) FCC Rules require the identification of all signal paths, clocks and oscillators in any block diagram. Please submit a corrected Block Diagram indicating the frequency of the “crystal”.

ANS: An updated block diagram was uploaded

4.) Please confirm – yes or no – if this device is capable of transmitting when inserted in the PCMCIA slot of a personal computer.

ANS: No.

Please review

Thanks for your help.

Daphne