



Wistron Corporation  
21th Fl., 88, Sec.1, Hsin Tai Wu Rd.,  
Hsichih, Taipei Hsien 221,  
Taiwan, R.O.C.  
Telephone: 886-2-8691-2888  
Facsimile: 886-2-8691-2080

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD. 21046

Date: Jan, 30, 2004

Page: 1 of 1

Attn: Equipment Authorization Branch

Subject: To CORRECT FCC ID in FORM 731  
Model No.: TravelMate C300  
Correct FCC ID: PU5MS2140AB

Dear Sir:

We would like to **CORRECT FCC ID** in **FORM 731** for the subject. The subject is a composite device for both Part 15C and 15E. Both of their IDs were mistyped on the FORM 731 as following:

	FCC Rule	Wrong FCC ID	Correct FCC ID
802.11b,Bluetooth	15C	PU5MS2140BG	PU5MS2140AB
802.11a	15E	PU5MS2140BG	PU5MS2140AB

I have found it was mistyped before uploading the files, but I cannot modify it. Except Form 731, the other files were all with the right ID. Please help me to correct it.

If you have any comments, please do not hesitate to contact us.

Yours sincerely,



Jammy Chen / Sr. Director  
Wistron Corporation