



Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_e.jpg

cB-0905-02 sample "16", top view


Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_h.jpg

cB-0905-02 sample "16", cover removed, top view


Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_b.jpg

cB-0905-02 sample "24", top view


Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_a.jpg

cB-0905-02 sample "24", cover removed, top view


Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_c.jpg

cB-0905-02 bottom view


Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_g.jpg

cB-0903-02, carrier board, top view

Annex B of test report R61184_A Edition 1
EUT: cB-0905-02
Manufacturer: connectBlue AB



61184_f.jpg

cB-0903-02, carrier board, bottom view