


120198\_09.JPG: EUT - internal, top view

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 1 of 8






120198\_10.JPG: EUT - internal, bottom view

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 2 of 8






122165\_11.JPG: EUT, main PCB, top view

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 3 of 8






122165\_12.JPG: EUT, main PCB, bottom view

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 4 of 8






122165\_13.JPG: EUT, RF PCB, top view - with shielding

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 5 of 8






122165\_15.JPG: EUT, RF PCB, top view - without shielding

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 6 of 8






120195\_14.JPG: EUT, RF PCB, bottom view

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 7 of 8





120195\_16.JPG: EUT, FCC label

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F120198E3

 Date of issue:
 21 January 2013
 Order No.:
 12-112165
 page 8 of 8