




120262_a.JPG: cB-0950 mounted on the cB-0903-03 (carrier board)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 1 of 8






120262_f.JPG: cB-0950 with internal antenna and additional voltage regulator, PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 2 of 8






120262_j.JPG: cB-0950 with antenna connector and without additional voltage regulator, PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 3 of 8





120262_g.JPG: cB-0950 with antenna port and additional voltage regulator, PCB, top view, shielding removed


 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 4 of 8



page 5 of 8

ANNEX B: INTERNAL PHOTOS OF THE EUT




120262_h.JPG: cB-0950 with antenna port and without additional voltage regulator, PCB, top view, shielding removed

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262





120262_e.JPG: cB-0950, PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 6 of 8





120262_b.JPG: cB-0903, PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 7 of 8





120262_c.JPG: cB-0903, PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F120262E1

 Date of issue:
 10 February 2012
 Order No.:
 12-120262
 page 8 of 8