

3301 E. Deseret Drive, St. George, UT 84790 www.wilsonelectronics.com • info@wilsonelectronics.com phone 1-800-204-4104 • fax 1-435-656-2432

August 21, 2024

Tuning and Adjustment of Wilson Model 460072 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to not exceed maximum gains, 28.6 dBm power level, and downlink dependent region (RSSI) set points as provided in the test results.

Sincerely,

fetel

Ilesh Patel Senior Engineering Product Manager