

**Note Regarding the On-board Shielding Covers**

The shielding covers are shown installed in the internal photos for model 271247-50.

The shielding covers have been removed in the internal photos for model 271247-75.