



3301 East Deseret Drive  
St. George, Utah 84790  
[www.wilsonelectronics.com](http://www.wilsonelectronics.com)  
[info@wilsonelectronics.com](mailto:info@wilsonelectronics.com)

Phone 800.204.4104 • Fax 435.656.2432

April 14<sup>th</sup>, 2011

TIMCO Engineering, Inc.  
849 N.W. State Road 45  
Newberry, FL 32669

Subject: Changes made to Model 271265 Signal Booster  
REF: FCC ID: PWO271265, IC: 4726A-271265

For purely commercial reasons, the outside case of the subject signal booster has been changed from a plastic case to a metal case. This is the only change made since the certification documents were presented to the FCC and Industry Canada. No electrical or other changes were made.

Photographs of the new metal case are attached.

Very truly yours,

A handwritten signature in blue ink, appearing to read 'Patrick Cook', is written over the closing text.

Patrick Cook  
Senior Electrical Engineer