



---

3301 East Deseret Drive  
St. George, Utah 84790

[www.wilsonelectronics.com](http://www.wilsonelectronics.com)  
[info@wilsonelectronics.com](mailto:info@wilsonelectronics.com)

Phone 800.204.4104 • Fax 435.656.2432

August 8, 2012

Tuning and Adjustment of Wilson Model 273470 Signal Booster

There are no external tuning adjustments. The installer adjusts the gain of the booster as explained in pages 10 through 13 of the User Manual. These adjustments are “fail safe” to prevent interference with cellular systems. If the adjustments are not made properly, the amplifier will either shut off or reduce its gain. Indication of these less than optimum conditions is evident by the booster’s LED indicator lights.

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick L. Cook', written in a cursive style.

Patrick L. Cook  
Senior Research and Development Engineer