



February 5, 2011

Booster Amplifier Model 2B1225 Tuning
FCC ID: PWO2B1225, IC: 4726A-2B1225

We hereby certify that there are no user accessible tuning or other adjustments in the Model 2B1225 booster amplifier. All adjustments are internal and only available to Wilson personnel during manufacturing (and repair if necessary).

Sincerely,

A handwritten signature in black ink that reads 'Richard M. Kline'.

Richard M. Kline
Senior Electrical Engineer