



Federal Communications Commission
Office of Engineering and Technology
Equipment Authorization Bureau

Attached please find a revised test report for Wilson Electronics amplifier FCC ID:PWO 2B1225. The original test report power output pages 12 and 13 contain numerical errors caused by incorrect application rounding of numbers and subsequent conversion. The power output values listed on the grant were not affected.

Regards,



Mario R. de Aranzeta
Engineer/ Lab Manager
Timco Engineering Inc.