



3301 East Desert Drive

St. George, Utah 84790

[www.wilsonelectronics.com](http://www.wilsonelectronics.com)

[info@wilsonelectronics.com](mailto:info@wilsonelectronics.com)

Phone 800.204.4104 • Fax 435.656.2432

March 1, 2011

Timco Engineering, Inc.  
849 NW State Road 45  
Newberry, FL 32669

Subject: Changes to User Manual for Signal Booster Model 2B1225, FCC ID: PWO2B1225, IC: 4726A-2B1225

Enclosed herewith is an updated User Manual (#110867\_DataProRev3.indd) for the subject equipment.

Changes that were made:

- correct typographical errors.
- add recommendations regarding electrical and lightning surge protection.
- recommend verifying that outside antenna installations meet requirements of relevant electrical codes.

Please remove the exhibit titled "installation guide" since this is for a different product and was uploaded in error.

Very truly yours,

A handwritten signature in black ink that reads 'Richard M. Kline'. The signature is written in a cursive style.

Richard M. Kline

Senior Electrical Engineer