



3301 East Deseret Drive  
St. George, Utah 84790  
[www.wilsonelectronics.com](http://www.wilsonelectronics.com)  
[info@wilsonelectronics.com](mailto:info@wilsonelectronics.com)

Phone 800.204.4104 • Fax 435.656.2432

October 15, 2012

Tuning and Adjustment of Wilson Model 2B3425 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to approximately  $27 \pm 2$  dBm.

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick L. Cook', is written in a cursive style.

Patrick L. Cook  
Senior Research and Development Engineer