



3301 East Deseret Drive  
St. George, Utah 84790  
[www.wilsonelectronics.com](http://www.wilsonelectronics.com)  
info@wilsonelectronics.com

Phone 800.204.4104 • Fax 435.656.2432

July 10, 2012

Tuning and Adjustment of Wilson Model 2B5325 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to approximately  $17 \pm$  3 dB gain.

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick L. Cook', written in a cursive style.

Patrick L. Cook  
Senior Research and Development Engineer