




Annex I


Oscillation Detection



Restart Time_Downlink_1962.5 MHz




Restart Time_Downlink_2132.5 MHz






Restart Time_Downlink_737 MHz




Restart Time_Downlink_751.5 MHz






Restart Time_Downlink_881 MHz




Restart Time_Uplink_1732.5 MHz






Restart Time_Uplink_1882.5 MHz




Restart Time_Uplink_707 MHz






Restart Time_Uplink_781.5 MHz




Restart Time_Uplink_836.5 MHz






Detection Time_Downlink_1962.5 MHz




Detection Time_Downlink_2132.5 MHz






Detection Time_Downlink_737 MHz




Detection Time_Downlink_751.5 MHz






Detection Time_Downlink_881 MHz




Detection Time_Uplink_1732.5 MHz






Detection Time_Uplink_1882.5 MHz




Detection Time_Uplink_707 MHz





Detection Time_Uplink_781.5 MHz



Detection Time_Uplink_836.5 MHz

