


Annex H


Occupied Bandwidth



Uplink_CDMA_1710-1755 MHz_Input




Uplink_CDMA_1710-1755 MHz_Output






Uplink_CDMA_1850-1910 MHz_Input




Uplink_CDMA_1850-1910 MHz_Output






Uplink_CDMA_698-716 MHz_Input




Uplink_CDMA_698-716 MHz_Output






Uplink_CDMA_776-787 MHz_Input




Uplink_CDMA_776-787 MHz_Output






Uplink_CDMA_824-849 MHz_Input




Uplink_CDMA_824-849 MHz_Output






Uplink_GSM_1710-1755 MHz_Input




Uplink_GSM_1710-1755 MHz_Output






Uplink_GSM_1850-1910 MHz_Input




Uplink_GSM_1850-1910 MHz_Output






Uplink_GSM_698-716 MHz_Input




Uplink_GSM_698-716 MHz_Output






Uplink_GSM_776-787 MHz_Input




Uplink_GSM_776-787 MHz_Output






Uplink_GSM_824-849 MHz_Input




Uplink_GSM_824-849 MHz_Output






Uplink_WCDMA_1710-1755 MHz_Input




Uplink_WCDMA_1710-1755 MHz_Output






Uplink_WCDMA_1850-1910 MHz_Input




Uplink_WCDMA_1850-1910 MHz_Output






Uplink_WCDMA_698-716 MHz_Input




Uplink_WCDMA_698-716 MHz_Output






Uplink_WCDMA_776-787 MHz_Input




Uplink_WCDMA_776-787 MHz_Output






Uplink_WCDMA_824-849 MHz_Input




Uplink_WCDMA_824-849 MHz_Output






Downlink_CDMA_1930-1990 MHz_Input




Downlink_CDMA_1930-1990 MHz_Output






Downlink_CDMA_2110-2155 MHz_Input




Downlink_CDMA_2110-2155 MHz_Output






Downlink_CDMA_728-746 MHz_Input




Downlink_CDMA_728-746 MHz_Output






Downlink_CDMA_746-757 MHz_Input




Downlink_CDMA_746-757 MHz_Output






Downlink_CDMA_869-894 MHz_Input




Downlink_CDMA_869-894 MHz_Output






Downlink_GSM_1930-1990 MHz_Input




Downlink_GSM_1930-1990 MHz_Output






Downlink_GSM_2110-2155 MHz_Input




Downlink_GSM_2110-2155 MHz_Output






Downlink_GSM_728-746 MHz_Input




Downlink_GSM_728-746 MHz_Output






Downlink_GSM_746-757 MHz_Input




Downlink_GSM_746-757 MHz_Output






Downlink_GSM_869-894 MHz_Input




Downlink_GSM_869-894 MHz_Output






Downlink_WCDMA_1930-1990 MHz_Input




Downlink_WCDMA_1930-1990 MHz_Output






Downlink_WCDMA_2110-2155 MHz_Input




Downlink_WCDMA_2110-2155 MHz_Output






Downlink_WCDMA_728-746 MHz_Input




Downlink_WCDMA_728-746 MHz_Output






Downlink_WCDMA_746-757 MHz_Input




Downlink_WCDMA_746-757 MHz_Output





Downlink_WCDMA_869-894 MHz_Input



Downlink_WCDMA_869-894 MHz_Output

