



American Certification Body Inc.
6731 Whittier Ave., Suite C110, McLean, VA 22101

June 25, 2012

RE: ATCB012410 – Original Equipment Certification Application – Model: RC603

FCC ID: PWR-RC60X for Trimble, Inc.

I have a few comments on this Application. Please **do not put confidential information** in your responses to these questions because the response letter will not be held confidential by the FCC. Depending on your answers there may be more questions.

1. The FCC portion of this application is in for CB review and release of the FCC grant of Certification. Unfortunately the CB has discovered two separate problems with the FCC ID label as follows:
 - (a) The FCC generally does not allow the FCC ID number to be placed on the battery compartment of a device. A label placed on a battery compartment door is not considered “permanent” as specified in Section 2.926(d) (and following paragraphs) of the FCC Rules because it can easily be broken off and lost. When it contains the FCC label, the label will be lost too. ACB is aware of only two instances where this FCC policy has been relaxed: (1) When the battery compartment door and the attaching hinge is made of metal so the door cannot be broken off or (2) the battery compartment door is made of a “hardened” or “industrial” plastic that will not break off during use. Please describe how the label on the battery compartment door meets either of these two exceptions or move the label to a permanent part of the exterior case of the device.

Response: this is the response from my customer:

the hinge for the battery door RC603 is a metal part. So this should be pretty clear and it can be seen at the sample we provided to you.

The material we use for the battery door it is our understanding that this is an “industrial” plastic; I have attached the data sheet. See uploaded document “LEXAN_243R Resin.pdf”.

- (b) The FCC ID label shown in the external photos exhibit has the wrong FCC ID number on it. The FCC looks for consistency in all exhibits and this label is different that the one shown on the label exhibit. I saw this discrepancy in the label exhibit where the picture showing the label location had the wrong FCC ID number but I missed this fact in the external photos exhibit. Please address.

Response: this is corrected, see uploaded document “10_Rev01_PWR-RC60X_External Photographs.pdf”.

Richard Tolson

Richard Fabina

Examining Engineer

[mailto: rfabina@acbcert.com](mailto:rfabina@acbcert.com)

Phone: 703-635-2881

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the www.acbcert.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.