



Sony Ericsson

Sony Ericsson Mobile Communications (USA) Inc.
7001 Development Drive
RTP, North Carolina 27709

February 03, 2003

American Telecommunications Certification Body Inc.
6731 Whittier Ave
McLean, VA 22101

Attention: Equipment Authorization Branch
Subject: Response to FCC Comments for FCC ID: PXITR-CA0802
Reference: Sony Ericsson Model T608

Dear Mr. Graff:

The attached page contains response to FCC comments concerning application for FCC certification of Sony Ericsson model T608 bearing FCC ID: PXITR-CA0802
If you have any questions and/or comments, please don't hesitate to make contact.

Sincerely,

Pierre Chery
Technical Manager, Type Approval
Research Triangle Park, NC
Tel No: (919) 472-1697
Fax No:(919) 472-6382
Pierre.chery@sonyericsson.com



Sony Ericsson

Sony Ericsson Mobile Communications (USA) Inc.
7001 Development Drive
RTP, North Carolina 27709

Request for additional information – Dated 12/10/2002 from FCC Martin Perrine

Please update the user manual body-worn statement. The following statement does not refer to the specific accessories tested. Also, the company Sprint did not approve any accessory. Sony-Ericsson is the responsible applicant here.

“use the Sprint approved carrying case,
holster or other accessory. Use of non-Sprint approved accessories
may violate FCC RF exposure guidelines.”

Body-Worn operation section of the user-manual has been updated. Reference to Sprint approved accessory is removed. Statement wording is now consistent with Supplement C of OET Bulletin 65. Revised user-manual was uploaded to ATCB server and a copy attached with this correspondence for your reference.