
Class II Change Letter

Dated this 2006/5/19

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oaklmd Mills Road
Columbia, MD 21046
U.S.A.

To whom it may concern,

We, Sporton International Inc., authorized by and on behalf of Netgear Incorporated would like to declare that the product with FCC ID: PY306100037 has been changed on some of the components of the basebase circuit. The indications are C38, R30, C37 and C47. No RF circuit as well as RF component has been changed. The value please see below:

C37: MC (G) 1000pF 50V

C47: MC (G) 1000pF 50V 10%(K) X7R 0402

C38: MC (G) 10pF 50V 5%(J)

R30: R (R) 33 ohm 1/16W

Sincerely yours,

Signature : 

Name/Title : Wayne Hsu / Supervisor

Company : Sporton International Inc.

Address : No. 52, Hwa Ya 1st Road., Kwei-Shan
Hsiang, TaoYuan Hsien Taiwan R.O.C.

Tel. No. : 886-3-3273456 ext 527

E-Mail : TCB@sporton.com.tw
