FCC ID: PY306100040
Description of Permissive Change
This report is prepared for FCC class II permissive change. The difference compared with the original design are re-layout to remove temporary EMC solution adopted in previous version.

Report No.: RF950329L08A