

# Netgear Incorporated

350 East Plumeria Drive San Jose California, United States 95134  
TEL: 408-89-3657 FAX: 408-907-8097

## Expedited Review Letter

Date: 2020-07-15


To: Federal Communications Commission  
Equipment Authorization Division

Subject: Expedited Review Approval

FCC ID: PY320100490

We, the undersigned, NETGEAR, Inc., declare that the FCC ID: PY320100490 is identical to the same performance and function as previously certified DFS tested and approved FCC ID: PY318200414. The differences are as the table below:

FCC ID of previously granted device FCC ID: PY318200414	FCC ID of new application FCC ID: PY320100490
<b>Technology:</b> MU-MIMO 802.11a/b/g/n/ac/ax RF chipset: BRCM43684	Same as previous
<b>Bandwidth information and differences:</b> 20MHz,40MHz,80MHz,160MHz	Same as previous
<b>Differences in DFS functioning, circuitry, software:</b> RF chipset BRCM43684 Wi-Fi Chipset driver version 17.10 RC25.1503	Same RF Chipset Same Chipset driver version Same DFS functionality and behavior Same DFS circuit design  Difference: Configure 5G as 2x2 in PY320100490
<b>Differences between the products:</b> Modulation: OFDM,OFDMA, and DSSSS Antenna Type: external dipole antenna Antenna directional gain: 5.25 GHz- 5.35 GHz, 5.56 dBi 5.47 GHz- 5.720 GHz, 6.22 dBi	Modulation: Same as the previous. Antenna Type: Same as the previous. Antenna directional gain: 5.25 GHz- 5.35 GHz, 6.05 dBi 5.47 GHz- 5.720 GHz, 6.24 dBi  Data processing circuitry is different. PCB layout is different. Enclosure is different
<b>Name of test labs for the grants:</b> Test Lab: Bureau Veritas CPS (H.K.) Ltd., Taoyuan Branch	Bureau Veritas CPS (H.K.) Ltd., Taoyuan Branch



David Kay / Director, Regulatory Compliance

Tel: 4088903657

Fax: 4089078097

E-Mail: david.kay@netgear.com