
FCC TEST REPORT Report No.: F2D1803

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW


SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

Page No. : 1 of 3 Issued Date : Feb. 25, 2003

: PY3MR814V2

FCC ID

FCC TEST REPORT Report No. : F2D1803



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : PY3MR814V2

 TEL: 886-2-2696-2468
 Page No.
 : 2 of 3

FAX: 886-2-2696-2255 Issued Date: Feb. 25, 2003


FCC TEST REPORT Report No.: F2D1803

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : PY3MR814V2
Page No. : 3 of 3
Issued Date : Feb. 25, 2003