

Class II change apply for WG302 (From WG302 ,FCC ID: PY3WG302)


- (1) Adding two new antennas.
- (2) Change the the RJ-45 LAN Port.

The difference as following:

(1) Original Antennas.



Model:ANT24O5 2.4GHz Ceiling 5dBi Antenna



Model:ANT24P12 2.4GHz GP Omni-directional 12dBi Antenna



Model:ANT24D18 2.4GHz Patch 18dBi Antenna

(1) Class II change Antennas.




Model:SNW0007A 2.4GHz 1/2λ Dipole 5dBi



Model:ANT24P9 2.4GHz GP Omni-directional 9dBi

(2) Original RJ-45 LAN Port.



(2) Class II change RJ-45 LAN Port.

