Setup Photographs

<Radiated Emission>

From 9kHz~30MHz



Rear View

Page Number : 1 of 2
Report Issued Date : Jul. 27, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2

Report No.: FR742207-01D

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PY7-32032B

Report No.: FR742207-01D

From 30MHz~1GHz

Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PY7-32032B Page Number : 2 of 2
Report Issued Date : Jul. 27, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2