
Setup Photographs


<Radiated Emission>

From 9kHz~30MHz



Report No.: FR692209-01D

Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PY7-33681M Page Number : 1 of 3
Report Issued Date : Feb. 06, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2

Report No. : FR692209-01D

From 30MHz~1GHz

Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PY7-33681M Page Number : 2 of 3
Report Issued Date : Feb. 06, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2

Verification of Radiated Spurious Emissions at open-area test site From 9kHz~30MHz



Report No. : FR692209-01D

Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: PY7-33681M Page Number : 3 of 3
Report Issued Date : Feb. 06, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 1.2