

Confidential REPORT Document number

2019-04-08

# FCC ID: PY7-61362R Internal Photo

#### Without Rear panel



#### Without PBA and Battery



#### **Rear panel**




It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.


Revision PA1 SONY

Revision PA1

### Internal PWB with Shield cases (Front-side)



#### Internal PWB without Shield cases (Front-side)






Revision PA1

3(5)

#### Internal PWB with Shield cases (Rear-side)



## Internal PWB without Shield cases (Rear-side)




SONY

## USB-FPC (Front)



## USB-FPC (Rear)



Revision PA1

# SONY

Revision PA1

## Battery:

	18W50 13 S/N 0C	815-7600 3159SWB	). 1C WMT	
SONY	18 制造日期·MC			
	U-Polymer Battery • 电池阳•二次建電池田 11	CP6/53/75	Ver/	
	701ERPC 東尼移动通信 電整 • Non. 3 85V 充电		X	
	容量 • Min. 3200 mAh 12.4 3330 mAh 12.9 Wh Made		1a	
注意:只能使用索!	· 有限公司为索尼移动通信产品 已移动通信产品(中国)有限公		A	
CAUTON: Durist not	中可能引起爆炸!不可抵日 work_disaccentra_stort	0	63	
C Allanne and		I Li	-ion 00	
日本 大田 外辺 単	更換不正確會有爆炸的危險	國際製造市政研署	遺理用語之事:	

