


Revision PA1


1(5)

FCC ID: PY7-77089S Internal Photo

Without Rear panel



Without PBA and Battery



Rear panel




It is the responsibility of the user to ensure that they have a correct and valid version. Any outdated hard copy is invalid and must be removed from possible use.


2(5)

Revision PA1


Internal Main-PWB Front with Shield cases(Front-side)



Internal Main-PWB Front without Shield cases (Front-side)




Internal Main-PWB Front (Rear-side)




3(5) Revision

PA1


Internal Main-PWB Rear with Shield cases (Rear-side)



Internal Main-PWB Rear without Shield cases (Rear-side)



Internal Main-PWB Rear with Shield cases (Front-side)






4(5) Revision

PA1

Internal Main-PWB Rear without Shield cases (Front-side)



Internal Sub-PWB (Front-side)

		日本でですの日	化合成 化合合成 化	· · · · · · · · · · · · · · · · · · ·
雷 孝 帝 !	* * * * *			*******
春 病 章	Q R 9 40 10 A		6 4 9 9 9 4 8	*******
~ ~ ~ ~ ~	5 5 4 th m g		****	*******
1 million	Designation of the local division of the loc	Restard a loss of the state of the state of the	Summer services and	anonce some dominant of Basson
000	0 0 4 4 1 1 A			2-5 2 0 6 × 8 2 6
0 0 0				
		10 4000		
	0.0			
And the second second	Contraction of the second second	10.50		
	A A A A A A A A A A A A A A A A A A A	L'EE	and the second second second	and the second se

		7MV-2 VØ		
10 10 10 10	4 0 M M		1111	****
***	9 9 <u>8 6 6 9</u> 9	11.		01
	4 4 4 1 1 1 4			*****
6 6 6 F	4 4 4 4 4 4		05 28	
Internet (1944)	Concernment of the	Benering 🗐 🚺		Contraction of the owner
6 10 10 1	****		*****	
際いの際にし際しい	E MILLING CHILLING	and the transmission	and a state of the state of the	
000	680848	PISPIPITE	FILTPIT	thinginging
* * *		hid b at a lat	1 F 101 9 101 9 F 1	
10 41 H	******	2 2 2 2 2 2 2	8 8 2 2 2 2 2	8 6 5 5 5 5 5 F 5 5
4 4 4				
Bassianterries	Lenosmanny	200000		*********
* * *	1.		and the second se	and the second
0 0 0		9.0.9 2 8 6		
		· · · · · · · · · · · · · · · · · · ·		

Internal Sub-PBA (Rear-side)

	mitorii				
	0 0 0 11 0		****	****	
10	A CONTRACTOR OF		and the second	SADDERS ADDRESS ADDRESS	Gerterotiste
	·····································			****	***
			0000000		
	* * * **** *		4 5 8 8 8 8	0. 000000	
	0 0		a s a a a a		0 10 10 10
	A A				
	State of the state		Manufacture in the local database		- and the second second
母命 章 商	R R B C 8	B (1000) + 9 + 1	05-28 U		***
林田田日	4 4 4 1 1 1 4	CO Latitudes		11 () 5 P P F	***
金石 白 麗		and there are		S1 2 8 8 8 8	
* * * *	10 10 10 10 10 10			100000	***
0 0 0 0	4 4 4 4 4	1 11H 1 11H		Eleeess	
and a second second	And a Conception of Conception of Conception	PROPERTY AND ADDRESS OF THE OWNER	ni 1	And and a second	
+ + (m)					2.0.0
A 40 10 10 3	BUR BUR BURE	2 8 8 848 8 8 4 1			
		I had had had had			ICITI
		ritritri	FITTER	THTSHT	1 + 1-1 +
				0 0 0 0 0 0 0 0 0	* * *
0 & 9 W	6 * * * * * * *	2000000			
and the second second second	CONSCIENCTION OF CONSCIENCE	Contractor and the second	and buildes and strand provident of	A surgery and the surgery and	L
新 雅 雅 雅				D	00 0 0
照 版 版 版	9 8 8 8 8 8	Annan			D
6 6 9 A					
命 単 体 版	****				
the to see it ?	A LA CAR CARA A		******		



5(5) Revision

PA1

Battery:

