

FIH CO., Ltd.

No.151, Sec. 1, Nankan Rd., Lujhu District, Taoyuan City 33859, Taiwan (R.O.C.)

Tel: +886-3-270-0000 ; Fax: +886-3-270-0001

Date: March 4, 2015

Variation Attestation

We hereby declares devices identified as

FCC ID: PY7-PM0785; IC: 4170B-PM0785

FCC ID: PY7-PM0781

FCC ID: PY7-PM0782

FCC ID: PY7-PM0787

FCC ID: PY7-PM0784 are the variants of FCC ID: PY7-PM0780.

Difference are listed as below

FCC ID	PY7-PM0780	PY7-PM0781	PY7-PM0785	PY7-PM0782	PY7-PM0787	PY7-PM0784
IC ID	N/A	N/A	4170B-PM0785	N/A	N/A	N/A
WCDMA Band	1, 2, 5, 8	1, 2, 5, 8	1, 2, 4, 5, 8	1, 2, 5, 8	1, 2, 5, 8	1, 2, 4, 5, 8
LTE Band	1, 2, 3, 5, 7, 8, 20	1, 2, 3, 5, 7, 8, 20	2, 4, 5, 7, 12, 13, 17, 28	1, 3, 5, 7, 8, 28	1, 3, 5, 7, 8, 28	Not Support
SIM Slot	Single SIM	Dual SIM Dual Standby	Single SIM	Single SIM	Dual SIM Dual Standby	Dual SIM Dual Standby
HAC	Not Support	Not Support	Support	Not Support	Not Support	Support

Except items above, the PCB/trace layouts, product form factor and antenna between these variants remain identical.

Based on the similarity between these devices, we hereby request to leverage the test data of FCC ID: PY7-PM0780 to demonstrate the compliance of FCC ID: PY7-PM0785/ IC: 4170B-PM0785; FCC ID: PY7-PM0784; FCC ID: PY7-PM0781; FCC ID: PY7-PM0787; FCC ID: PY7-PM0782 regarding to FCC Part 2.1093/22H/24E/27 and IC RSS-102/RSS-133/RSS-139/RSS-132/RSS-199/RSS-130 requirements.

The worst cases found in FCC ID: PY7-PM0780 are verified in FCC ID: PY7-PM0785/ IC: 4170B-PM0785; FCC ID: PY7-PM0784; FCC ID: PY7-PM0781; FCC ID: PY7-PM0787; FCC ID: PY7-PM0782 to ensure the compliance is kept.

Sincerely yours,

A handwritten signature in black ink that reads "Hugo Shieh". The signature is written in a cursive style with a horizontal line underneath it.

Hugo Shieh / Supervisor
hugoshieh@fihspec.com