

Sony Mobile Communications Prepared by SEM/CGVFDB KEIGO OSHIRO Contents responsible if other than preparer

Approved by

Company Internal REPORT Document number 39/0360-LXE 110 1383 Uen Date 2015-04-06 Remarks This document is managed in metaDoc. 1(5)

Revision PA1

PY7-PM0794: Internal Photos:

Without Rear Panel



With PWB





Revision PA1


2(5)

Without PWB






Internal PWB with/without Shield cases – Front (LCD)-side:




Internal PWB with Shield cases (Front-side)



Internal PWB without Shield cases (Front-side)



Internal PWB with/without Shield cases - Rear-side:



Internal PWB with Shield cases (Rear-side)



Internal PWB without Shield cases (Rear-side)

SONY

Revision PA1

5(5)

Battery:



