
Order Number:	11139405	Report Number:	R11139405C-E2	Page	15 of 29
FCC ID:	PY7-PM0942	-		-	
Client Name:	Sony Mobile Communications Inc.		lssued: 2016-04-25		


Figure 1 Test Setup for Conducted Emissions



Note: Laptop Ethernet was plugged into facility wall jack that was connected to facility switch, running ping session.

Order Number:	11139405	Report Number:	R11139405C-E2	Page	23 of 29
FCC ID:	PY7-PM0942				
Client Name:	Sony Mobile Communications Inc.			lssued: 2016-04-25	

Figure 4 Test setup for Radiated Emissions < 1GHz



Order Number:	11139405	Report Number:	R11139405C-E2	Page	24 of 29
FCC ID:	PY7-PM0942	-		-	
Client Name:	Sony Mobile Communications Inc.			Issued: 2016-04-25	




Figure 5 Test setup for Radiated Emissions > 1GHz

UL LLC | 12 Laboratory Dr. | Research Triangle Park, NC 27709 USA | Tel.: 919 549-1400 | Rev. No 1.0 EMC Report 2012-87-EM-F0042