

# SPORTON INTERNATIONAL INC.

No. 52, Hwa Ya 1st Rd., Hwa Ya Technology Park, Kwei-Shan Hsiang, Taoyuan Hsien, Taiwan  
Tel: +886 3 327 3456 ; Fax: +886 3 328 4978

Dear Examiner,

Regarding the FCC ID: PY7-PM0961 application, we confirm that, the test results in the report should relate to the EUT software version of "37.0.A.0.19", and the information listed on the current test reports is incorrect.

- Incorrect software version: 33.2.A.0.19
- Correct software version: 37.0.A.0.19

We request permission to supersede the test reports to reflect the correct software version.

If you have any question regarding this application, please feel free to contact me.  
Respectfully,



---

Jones Tsai  
Lab Manager  
Sporton International Inc.  
JonesTsai@sporton.com.tw