



Vår handläggare, namn, tfn .Attending to this matter, name, telephone number

Ert datum. Your date

Er beteckning - Your reference

Document number

BGLI08:901

Dale

2008-10-31

Remarks

Revision

A

Prepared by

SEM/BGLIVM Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Approved by

SEM/BGLIVMC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and Certification and Engineering Bureau Industry Canada

Application PY7A3252081,

4170B-A3252081

Statement on WLAN hardware

Sony Ericsson mobile phone G705a (FCC ID PY7A3252081, IC: 4170B-A3252081) uses the exact same WLAN hardware and software as G705u (FCC ID PY7A3252081, IC: 4170B-A3252081).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-53-07108-A, dated 2008-10-12) issued for G705u also applies for G705a.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail SE-221 88 Lund Sweden

Besöksadress • Office address Nya Vattentornet Lund

Styrelsens säte: Lund Registered office: Lund Telefon • Telephone Nat 046-19 40 00 Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801 Organisationsnr • Reg No: 556615-6658 Telefax • Telefax Nat 046-19 41 00 Int +46 46 19 41 00