



Sony Ericsson

Datum. Date

Beteckning. Reference

Vår handläggare, namn, tfn • Attending to this matter, name, telephone

Ert datum • Your date

Er beteckning • Your reference

Document number

Revision

BGLI08:991

A

Date

2008-12-23

Remarks

Prepared by

SEM/BGLIVM Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Approved by

SEM/BGLIVMC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type Number AAD-3880005-BV , FCC ID: **PY7A3880005**,

Canada IC: 4170B-A3880005

Statement on WLAN hardware

Sony Ericsson mobile phone W705a (FCC ID PY7A3880005, IC: 4170B-A3880005) uses the exact same WLAN hardware and software as W705 (FCC ID PY7A3880006, IC: 4170B-A3880006).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-63-07/08, dated 2008-11-13) issued for W705 also applies for W705a.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00