



Confidential

1(1)

Document number
CCDA09:347

Revision
A

Date
2009-07-01

Remarks

Prepared by

SEM/CCDALE Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Approved by

SEM/CCMVA Mats Hansson + 46 10 802 33 57

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application Type number: AAD-3880033-BV,

FCC ID: PY7A3880033,

Canada IC: 4170B-A3880033

Statement on WLAN hardware

Sony Ericsson mobile phone U10a (FCC ID PY7A3880033, IC: 4170B-A3880033) uses the exact same WLAN hardware and software as U10i (FCC ID PY7A3880032, IC: 4170B-A3880032).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1065-34-06/09, dated 2009-06-18) issued for U10i also applies for U10a.

Best regards,

Mats Hansson

Head of Regulatory Compliance

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00