



Confidential

1(1)

Document number  
CCDA09:622  
Date  
2009-12-09  
Remarks

Revision  
A

Prepared by  
SEM/CCDALE Afrah Sadiq + 46 10 80 12250  
Contents responsible if other than preparer

Approved by  
SEM/CCDALEC Peter Lindeborg + 46 10 802 43 68

Receiver: Federal Communication Commission and  
Certification and Engineering Bureau  
Industry Canada

**Application Type number: AAD-3880059-BV,**  
**FCC ID: PY7A3880059,**  
**Canada IC: 4170B-A3880059**

### Statement on WLAN hardware

Sony Ericsson mobile phone U5a (FCC ID PY7A3880059, IC: 4170B-A3880059) uses the exact same WLAN hardware and software as U5i (FCC ID PY7A3880058, IC: 4170B-A3880058).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1065-66-06/09, dated 2009-12-07) issued for U5i also applies for U5a.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail  
SE-221 88 Lund  
Sweden

Besöksadress • Office address  
Nya Vattentornet  
Lund

Styrelsens säte: Lund  
Registered office: Lund  
Telefon • Telephone  
Nat 046-19 40 00  
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801  
Organisationsnr • Reg No: 556615-6658  
Telefax • Telefax  
Nat 046-19 41 00  
Int +46 46 19 41 00