



Confidential

1(1)

Document number
CCDA09:593

Revision
A

Prepared by

SEM/CCDALE Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Date
2009-11-23
Remarks

Approved by

SEM/CCDALEC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type number: AAD-3880074-BV,

FCC ID: PY7A3880074,

Canada IC: 4170B-A3880074

Statement on Bluetooth hardware

Sony Ericsson mobile phone SO-01B (FCC ID: PY7A3880074, IC: 4170B-A3880074) uses the exact same Bluetooth hardware and software as Xperia X10i (FCC ID: PY7A3880056, IC: 4170B-A3880056).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1065-60-04/09, dated 2009-10-21) issued for Xperia X10i also applies for So-01B.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00