

Confidential

1(1)

Prepared by
SEMC/CVDVBA Afrah Sadiq + 46 10 80 12250
Contents responsible if other than preparer

Document number
CVDVBA11:067
Date
2011-03-04
Remarks

Revision
A

Approved by
SEMC/CVDVBA Johan Wedin Svensk tel +46 10 80 11987

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type number: AAD-3880087-BV,

FCC ID: PY7A3880087,

Canada IC: 4170B-A3880087

Statement on WLAN hardware

Sony Ericsson mobile phone R800a (FCC ID: PY7A3880087, IC: 4170B-A3880087) uses the exact same WLAN hardware and software as R800i (FCC ID: PY7A3880087, IC: 4170B-A3880087).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-2977-06-08/11, dated 2011-02-15) issued for R800i also applies for R800a.

Best regards,



Johan Wedin Svensk
Manager GSM/UMTS
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 010-80 00000
Int +46 10 80 00000

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 010-80 02040
Int +46 10 80 02040