

Confidential

1(1)

Prepared by

SEMC/CVVALG Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Document number

CVVA10:334

Date

2010-08-09

Remarks

Revision

A

Approved by

SEMC/CVVALG Johan Wedin Svensk tel +46 10 80 11987

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application Type number: AAD-3880092-BV,

FCC ID: PY7A3880092,

Canada IC: 4170B-A3880092

Statement on WLAN hardware

Sony Ericsson mobile phone E15a (FCC ID PY7A3880092, IC: 4170B-A3880092) uses the exact same WLAN hardware and software as E15i (FCC ID PY7A3880091, IC: 4170B-A3880091).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1954-31-06/10_E, dated 2010-07-20) issued for E15i also applies for E15a.

Best regards,



Johan Wedin Svensk
Manager GSM/UMTS
Sony Ericsson Mobile Communications (Sweden)AB

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 010-80 00000
Int +46 10 80 00000

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 010-80 02040
Int +46 10 80 02040